

VW3A9310

substitution kit for ATV38/58 - compatible with
ATV61/ATV71

Main

Commercial Status	Commercialised
Accessory / separate part category	Adaptation accessories
Accessory / separate part type	Adaptor
Accessory / separate part designation	Substitution kit for Altivar 38/58 drives
Product compatibility	ATV61HD22N4 ATV61HD30N4 ATV61HD30Y ATV71HD18M3X ATV71HD22N4 ATV71HD30N4 ATV71HD37N4 ATV71HU22Y...HD30Y
Accessory / separate part destination	Variable speed drive
Range compatibility	Altivar 61 Altivar 71
Product specific application	Substitution of an ATV38HD28N4X by an ATV61HD22N4 Substitution of an ATV38HD33N4X by an ATV61HD30N4 Substitution of ATV58HD12N4...HD33N4 by ATV71HD11Y...HD30Y Substitution of an ATV58HD23M2X by an ATV71HD18M3X Substitution of ATV58HD29N4...HD72N4 by ATV71HU22Y...HU75Y Substitution of an ATV38HD28N4 by an ATV61HD22N4 Substitution of an ATV38HD33N4 by an ATV61HD30N4 Substitution of an ATV58HD18N4 by an ATV71HU22Y Substitution of an ATV58HD28N4 by an ATV61HD30Y Substitution of an ATV58HD28N4 by an ATV71HD22N4 Substitution of an ATV58HD28N4 by an ATV71HD30Y Substitution of an ATV58HD33N4 by an ATV71HD22N4 Substitution of an ATV58HD33N4 by an ATV71HD30N4 Substitution of an ATV58HD46N4 by an ATV71HD30N4 Substitution of an ATV58HD46N4 by an ATV71HD37N4 Substitution of an ATV58HD54N4 by an ATV71HD37N4

Contractual warranty

Period	18 months
--------	-----------

The information provided in this documentation contains general descriptions and/or technical characteristics of the products contained herein. This documentation is not intended as a substitute for and is not to be used for determining suitability or reliability of these products for specific user applications. It is the duty of any such user or integrator to perform the appropriate and complete risk analysis, evaluation and testing of the products with respect to the relevant specific application or use thereof. Neither Schneider Electric Industries SAS nor any of its affiliates or subsidiaries shall be responsible or liable for misuse of the information contained herein.