Tools for contacts Han E[®] (09 33 ...)



| Insertion tool for crimp contacts | Part number 09 99 000 0059 | For crimp contacts with wires of less than 0.75 mm² it is recommended that an insertion tool is used. Contacts should be inserted from the wiring side and pushed down until a positive locking is achieved. |
|---|-----------------------------|--|
| Insertion tool for Han® ES inserts | 09 99 000 0367 | |
| Removal tool for crimp contacts for Han® EE, Han® Q 5/0, Han® Q 8/0, Han E®, Han- Yellock® and Han A® | 09 99 000 0319 | A removal tool is necessary if contacts are to be replaced in the insert. The tool is inserted from the wiring side until a stop is noticeable. The wire with the crimp contact can then be pulled out from the same side of the insert. |
| | | |
| | | |
| | | |
| | | |
| | | |