


Accessories

Strain Relief Plates (For In-The-Field Assembly or Factory-Assembled)

MCS-MIDI

<p>Strain relief plates for in-the-field assembly Pin spacing 5/5.08 mm</p> <p>for female connectors with CAGE CLAMP®S (2721, 2231 and 2-conductor 231, 721 Series)</p>	<p>Strain relief plates for in-the-field assembly Pin spacing 7.5/7.62 mm</p> <p>for female connectors with CAGE CLAMP®S (2721, 2231 and 2-conductor 231, 721 Series)</p>	<p>Strain relief plates, factory-assembled</p> <p>for female connectors with CAGE CLAMP®S (2721, 2231 and 2-conductor 231, 721 Series)</p>
------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------



Width	Pole No.	Item No.	Pack. Unit	Width	Pole No.	Item No.	Pack. Unit	Width	Item No. Suffix
Strain relief plate, light gray				Strain relief plate, light gray				Strain relief plate, pre-assembled	
6 mm	2	734-127	100 (4 x 25)	6 mm		734-127	100 (4 x 25)	6 mm	.../132-000
12.5 mm	3- 4	734-128	100 (4 x 25)	12.5 mm	2- 3	734-128	100 (4 x 25)	12.5 mm	.../133-000
25 mm	5- 7	734-129	100 (4 x 25)	25 mm	4- 6	734-129	100 (4 x 25)	25 mm	.../134-000
35 mm	8-11	734-126	100 (4 x 25)	35 mm	7- 9	734-126	100 (4 x 25)	35 mm	.../135-000
55 mm	12-16	734-426	50 (2 x 25)	55 mm	10-12	734-426	50 (2 x 25)	55 mm	.../136-000
75 mm	17-24	734-427	50 (2 x 25)	75 mm	13-16	734-427	50 (2 x 25)	75 mm	.../137-000
Strain relief plate, gray				Strain relief plate, gray				Ordering example: 2-conductor female connector with strain relief plate, 5 mm pin spacing, 8-pole, gray: 231-2108/026-000/135-000	
6 mm	2	734-327	100 (4 x 25)	6 mm		734-327	100 (4 x 25)	Ordering example: Female connector with push-buttons and strain relief plate, 7.5 mm pin spacing, 8-pole, gray: 2231-208/026-000/135-000	
12.5 mm	3- 4	734-328	100 (4 x 25)	12.5 mm	2- 3	734-328	100 (4 x 25)		
25 mm	5- 7	734-329	100 (4 x 25)	25 mm	4- 6	734-329	100 (4 x 25)		
35 mm	8-11	734-326	100 (4 x 25)	35 mm	7- 9	734-326	100 (4 x 25)		
55 mm	12-16	734-430	50 (2 x 25)	55 mm	10-12	734-430	50 (2 x 25)		
75 mm	17-24	734-431	50 (2 x 25)	75 mm	13-16	734-431	50 (2 x 25)		
Strain relief plate, orange				Strain relief plate, orange				CAGE CLAMP®S-equipped female connectors can be retrofitted with a strain relief plate or pre-assembled with one at the factory. An "item no. suffix", referring to the width of the strain relief plate, is added to the "basic item no." and determines the type of connector (see ordering examples).	
6 mm	2	734-227	100 (4 x 25)	6 mm		734-227	100 (4 x 25)	The arrangement of the attachments for cable ties allows single conductors or multi-core cables to be secured in different ways	
12.5 mm	3- 4	734-228	100 (4 x 25)	12.5 mm	2- 3	734-228	100 (4 x 25)		
25 mm	5- 7	734-229	100 (4 x 25)	25 mm	4- 6	734-229	100 (4 x 25)		
35 mm	8-11	734-226	100 (4 x 25)	35 mm	7- 9	734-226	100 (4 x 25)		
55 mm	12-16	734-428	50 (2 x 25)	55 mm	10-12	734-428	50 (2 x 25)		
75 mm	17-24	734-429	50 (2 x 25)	75 mm	13-16	734-429	50 (2 x 25)		

WAGO does not offer the recommended cable ties and cable binding tools; those are available from suppliers such as Hellermann. The width of the cable ties must correspond to the hole dimensions indicated for the strain relief plates.

