

Identification	Part number	Drawing	Dimensions in mm								
<p>HARTING Service crimping tool with locator for Han D[®], Han E[®],</p> <p>Locator Han-<i>Yellock</i>[®]</p>	<p>09 99 000 0021</p> <p>09 99 000 0343</p>	<p>Wire gauge 0.5 ... 2.5 mm²</p> 									
<p>BUCHANAN crimping tool</p> <p>Locator Han-<i>Yellock</i>[®]</p> <p>Multiple crimping tool depth adjustment gauge</p>	<p>09 99 000 0001</p> <p>09 99 000 0342</p> <p>09 99 000 0379</p>	<p>Wire gauge 0.14 ... 4 mm²</p>  <p>Wire gauge</p> <table border="0"> <tr> <td>0.14 ... 0.37 mm²</td> <td>Ø 1.00</td> </tr> <tr> <td>0.5 ... 1.0 mm²</td> <td>Ø 1.55</td> </tr> <tr> <td>1.5 ... 2.5 mm²</td> <td>Ø 1.80</td> </tr> <tr> <td>3.0 ... 4.0 mm²</td> <td>Ø 2.00</td> </tr> </table> 	0.14 ... 0.37 mm ²	Ø 1.00	0.5 ... 1.0 mm ²	Ø 1.55	1.5 ... 2.5 mm ²	Ø 1.80	3.0 ... 4.0 mm ²	Ø 2.00	
0.14 ... 0.37 mm ²	Ø 1.00										
0.5 ... 1.0 mm ²	Ø 1.55										
1.5 ... 2.5 mm ²	Ø 1.80										
3.0 ... 4.0 mm ²	Ø 2.00										
<p>HARTING crimping tool with locator for Han D[®], Han E[®], Han[®] C</p> <p>Locator Han-<i>Yellock</i>[®]</p>	<p>09 99 000 0110</p> <p>09 99 000 0341</p>	<p>Wire gauge 0.5 ... 4 mm²</p> 									
<p>HARTING crimping tool for Han-<i>Yellock</i>[®] PE Crimp contacts</p>	<p>09 99 000 0377</p>	<p>Wire gauge 6 ... 10 mm²</p> 									